

The speed recorded in the report is the last value recorded as the vehicle passes closest to the speed awareness device. The device is sited a significant distance inside the speed limit signs.







Data on 08/04/2020 missing due to a flat battery in the device on this occasion.