

East Haddon Road August 2020

The speed recorded in the report is the last value recorded as the vehicle passes closest to the speed awareness device. The device is sited a significant distance inside the speed limit signs.







Data is incomplete due to battery issues.