

## Coton Road June 2020

The speed recorded in the report is the last value recorded as the vehicle passes closest to the speed awareness device. The device is sited a significant distance inside the speed limit signs.







This is only a partial month as the device was moved on Saturday 13<sup>th</sup>.