

The speed recorded in the report is the last value recorded as the vehicle passes closest to the speed awareness device. The device is sited a significant distance inside the speed limit signs.







Partial data from February is also included in this report.

Data on 23/02/2020, 20/02/2020, 20/03/2020 and 29/03/2020 are incomplete due to a flat battery in the device on each occasion. Other days are completely missing due to the same issue.