

Coton Road May 2020

The speed recorded in the report is the last value recorded as the vehicle passes closest to the speed awareness device. The device is sited a significant distance inside the speed limit signs.







Data on 05/05/2020 - 06/05/2020 and 18/05/2020 - 20/05/2020 is missing due to a flat battery in the device on this occasion.